

Lead in water test taken 01/10/2023

<u>Test Number</u>	<u>East Campus Elementary</u>	<u>Lead Detection</u>	<u>Action Needed</u>
101	Room 1 sink	None/Detected	
103	Room 2 sink	N/D	
104	Room 2 fountain	N/D	
105	Room 3 sink	N/D	
106	Room 4 sink	N/D	
108	Room 5 sink	N/D	
109	Room 5 fountain	N/D	
110	Room 6 sink	N/D	
111	Room 6 fountain	N/D	
112	Room 7 sink	N/D	
113	Room 7 fountain	N/D	
114	Room 8 sink	N/D	
115	Room 9 sink	N/D	
116	Room 10 sink	N/D	
117	Room 11 sink	N/D	
118	Room 12 sink	N/D	
119	Room 13 sink	N/D	
120	Room 14 sink	N/D	
121	Room 15 sink	N/D	
122	Room 16 sink	N/D	
123	K1 Girls sink north	N/D	
124	K1 Girls sink center	N/D	
125	K1 Girls sink south	N/D	
126	K1 Boys sink north	N/D	
127	K1 Boys sink center	N/D	
128	K1 Boys sink south	N/D	
129	2nd Girls sink east	N/D	
130	2nd Girls sink west	N/D	
131	2nd Boys sink east	N/D	
132	2nd Boys sink west	N/D	
133	Exterior staff Rest Room sink	N/D	
134	Interior staff Rest Room sink	N/D	
135	Room 1 Rest Room sink	N/D	
136	Title Room sink	N/D	
137	Hall Drinking fountain	N/D	
138	Exterior drinking fountain north	N/D	
139	Exterior drinking fountain south	N/D	
140	Cafeteria drinking fountain	N/D	
141	Kitchen dish sink left	N/D	
142	Kitchen dish sink center	N/D	
143	Kitchen dish sink right	N/D	
144	Kitchen prep sink east	N/D	
145	Kitchen prep sink west	N/D	
146	Kitchen back sink left	N/D	

147	kitchen back sink right	N/D	
-----	-------------------------	-----	--

lead in water test taken 01/11/2023

<u>Sample ID</u>	<u>West Campus Elementary</u>	<u>Lead Detection</u>	<u>Action Needed</u>
201	Room 1 sink south	None Detected	
202	Room 1 sink west	N/D	
203	Room 1 sink north	N/D	
204	Room 2 sink	N/D	
205	Room 3 sink	N/D	
206	Room 3 fountain	N/D	
207	Room 4 sink	N/D	
208	Room 4 fountain	N/D	
209	Room 5 sink	N/D	
210	Room 6 sink	N/D	
211	Room 8 sink	N/D	
212	Room 9 sink	N/D	
213	Room 15 sink	N/D	
214	Room 16 sink	N/D	
215	Room 17 sink east	N/D	
217	Room 17 sink west	N/D	
216	Room 18 sink by door	N/D	
222	Room 19 sink	N/D	
223	Library sink	N/D	
224	Library Rest Room	N/D	
225	Conference Rest Room	N/D	
226	1st Aide Rest Room	N/D	
227	Main Hall Boys sink east	N/D	
228	Main Hall Boys sink west	N/D	
229	Main Hall Girls sink east	N/D	
230	Main Hall Girls sink west	N/D	
231	Outside Boys sink east	N/D	
232	Outside Boys sink west	N/D	
233	Outside Girls sink east	N/D	
234	Outside Girls sink west	N/D	
235	3rd Boys sink east	N/D	
236	3rd Boys sink center	N/D	
237	3rd Boys sink west	N/D	
238	3rd Girls sink east	N/D	
239	3rd Girls sink center	N/D	
240	3rd Girls sink west	N/D	
241	Girls Locker Room drinking fountain	disabled	test when fixed
242	Girls Locker Room sink south	N/D	
243	Girls Locker Room sink center	N/D	
244	Girls Locker Room sink north	N/D	
245	Boys Locker Room drinking fountain	disabled	test when fixed
246	Boys Locker Room sink south	N/D	

247	Boys Locker Room sink north	N/D	
248	Main Hall drinking fountain	N/D	
249	3rd Hall drinking fountain	N/D	
250	Playground drinking fountain	N/D	
251	Kitchen sink far west	N/D	
252	Kitchen sink west	N/D	
253	Kitchen sink east	N/D	
254	Kitchen sink far east	N/D	
255	Kitchen sink center	N/D	

lead in water test taken 01/13/2023

Sample ID	RR Jr/Sr High School	Lead Detection	Action Needed
301	Gym Drinking Fountain	None Detected	
302	Commons Drinking Fountain	N/D	
303	Jr Hall Drinking Fountain	N/D	
304	Work Room sink	N/D	
305	Staff Room sink	N/D	
307	Canteen sink	N/D	
308	Mens Staff Rest Room sink	N/D	
309	Womens Staff Rest Room sink	N/D	
310	1st Aide Rest Room sink	N/D	
311	Sr Hall Rest Room sink	N/D	
312	Jr Hall Rest Room sink	N/D	
313	Commons Rest Room sink	N/D	
314	Team Locker Room sink left	N/D	
315	Team Locker Room sink right	N/D	
316	Boys Locker Room sink left	N/D	
317	Boys Locker Room sink right	N/D	
318	Boys Locker Room coach sink	N/D	
319	Girls Locker Room sink left	N/D	
320	Girls Locker Room sink right	N/D	
321	Girls Locker Room coach sink	N/D	
322	Main Boys Rest Room sink 1 left	N/D	
323	Main Boys Rest Room sink 2	N/D	
324	Main Boys Rest Room sink 3	N/D	
325	Main Boys Rest Room sink 4	N/D	
326	Main Boys Rest Room sink 5 right	N/D	
327	Main Girls Rest Room sink 1 left	N/D	
328	Main Girls Rest Room sink 2	N/D	
329	Main Girls Rest Room sink 3	N/D	
330	Main Girls Rest Room sink 4	N/D	
331	Main Girls Rest Room sink 5 right	N/D	
332	Music Room sink	disabled	test when fixed
333	Art Room sink 1 left	N/D	
334	Art Room sink 2	N/D	
335	Art Room sink 3	N/D	

336	Art Room sink 4	N/D	
337	Art Room sink 5 right	N/D	
338	Room 31 sink	N/D	
341	Kitchen hand sink east	N/D	
342	Kitchen hand sink center	N/D	
343	Kitchen dish sink left	N/D	
344	Kitchen dish sink right	N/D	
345	Library back room sink	N/D	
346	Boys locker room Drinking Fountain	N/D	

lead in water tests taken 03/10/2021

<u>Sample ID</u>	<u>South Valley Academy</u>	<u>Lead Detection</u>	<u>Action Needed</u>
K	Kitchenette	None/Detected	none
MBI	Mens Rest Room sink	N/D	none
WB2A	Womens Rest Room sink 1	N/D	none
WB2B	Womens Rest Room sink 2	N/D	none
SB	Staff Rest Room sink	N/D	none
ADAB	ADA Restroom sink	N/D	none
ES	East Room Sink	N/D	none

lead in water tests taken 2023

<u>Sample ID</u>	<u>District Office</u>	<u>Lead Detection</u>	<u>Action Needed</u>
401	Kitchen sink		
402	Upstairs Rest Room sink		
403	Downstairs Rest Room sink		

lead in water tests taken 2023

<u>Sample ID</u>	<u>Misc. Locations in District</u>	<u>Lead Detection</u>	<u>Action Needed</u>
501	Beck Field concession sink		
502	Beck Field Boys Rest Room sink		
503	Beck Field Girls Rest Room sink		
504	Beck Field Drinkin Fountain		
505	JR/SR Soft Ball dugout home		
506	JR/SR Soft Ball dugout guest		
507	Drinking Fountain by Baseball		
508	Cheiftain Stadium Concession sink		
509	Cheiftain Stadium Boys RR sink left		
510	Cheiftain Stadium Boys RR sink right		
511	Cheiftain Stadium Girls RR sink left		
512	Cheiftain Stadium Girls RR sink right		
513	Bus Barn?		
514	Bus Barn?		
515	JR/SR AG Building boys RR sink		
516	JR/SR AG Building girls RR sink		
517	JR/SR AG Building staff RR sink		